

Safety Project Example

- **Observation**

- The Eastover, S.C., mill warehouse experienced severe condensation on floors after a few days of cooler weather followed by a quick rise in temperature with lots of humidity.

- **Issue**


- The condensation made it dangerous to operate clamp trucks in many areas.

- **Action**


- Cross-functional team members identified the safety issue and intentionally worked to make the floors safe again prior to putting anyone on the clamp trucks. Dehumidifiers, portable heaters and fans were used to dry impacted floors.

- **Result**

- While doing this, the team never compromised safety. People before paper prevailed.



BEFORE



AFTER

(Condensation drying out)